



- ① AVAMI N25 05.9 E055 56.8
- ② BUBIN N24 57.7 E056 06.7
- ③ ANVIX N24 46.9 E055 56.3
- ④ KANIP N24 10.7 E055 20.7
- ⑤ LABRI N24 03.7 E055 38.7
- ⑥ ITRAX N24 12.8 E055 47.8
- ⑦ TUKLA N25 19.6 E055 40.2
- ⑧ MUTVI N25 37.0 E054 55.6
- ⑨ RAGOL N25 27.7 E055 07.7
- ⑩ MEMBI N24 37.1 E054 26.5
- ⑪ GADVON24 41.4 E053 43.0
- ⑫ KUNGU N24 37.9 E053 56.5

All aircraft entering Sanaa FIR are required to contact SANAA CONTROL/RADIO at least 10 minutes prior to entering:
 - east sector from MUSCAT FIR on 132.2, or if unable on 11300, day 10018, 13288, night 5658
 - east sector from other FIRs on 132.2, or if unable on 125.7, 11300, day 10018, 13288, night 5658
 - west sector on 125.7

Contact Bahrain ACC at least 10 minutes prior to entering FIR.

Controlled airspace within Bahrain UIR is class (A)

Contact Emirates ACC 5 minutes prior crossing.

Westbound Traffic shall contact Muscat Control on 123.95 at ASPUX.

Airways TMA/UTA within Muscat FIR are class (A)

SANAA RADIO
 AFI 3
 ① 5658
 ② 10018
 ③ 11300
 ④ 13288
 MID 1
 7595
 @ NIGHT @ DAY

MUSCAT 123.95

EAST SECTOR
 SANAA
 132.20

-3=UTC
 -4=UTC